To: Matt Francis[m.francis@erllc.com]

Cc: Christoph Goss[christoph.goss@deereault.com]

From: Way, Steven

Sent: Thur 6/12/2014 9:34:21 PM Subject: FW: Pix of the Gold King

Matt.

Here are a couple shots from Wednesday at the Gold King mine. The significance of the rock face view is the shallow nature of the overburden before encountering fractured rock. The estimate from Bruce was 25 feet of colluvium. Also, the flow is exceptionally low from the adit whereas normally it is about $50-100~{\rm gpm}$ in this time of year.

Also, the only information available on the tunnel dimensions suggests it may be an 8×8 opening with flat roof/back.


Steve

From: Stover - DNR, Bruce [mailto:bruce.stover@state.co.us]

Sent: Thursday, June 12, 2014 2:46 PM

To: Way, Steven


Subject: Pix of the Gold King





--

Bruce K. Stover
Director
Inactive Mine Reclamation Program



P 303.866.3567 x <u>8146</u> | F 303.832.8106

1313 Sherman Street, Room 215, Denver, CO 80203 bruce.stover@state.co.us | http://mining.state.co.us